
















Översikt Strömtransformatorer

	<p>4R21.3 50 - 500A Håldiameter: 21 mm</p>		<p>6A315.3 50 - 750A Skena: 30 x 15 mm 20 x 20 mm</p>		<p>6A412.3 200 - 1000A Skena: 40 x 12 mm 2 x 30 x 10 mm</p>
	<p>7A412.3 50 - 1000A Skena: 40 x 12 mm 20 x 30 x 10 mm</p>		<p>7A512.3 125 - 1000A Skena: 50 x 12 mm 20 x 40 x 10 mm</p>		<p>8A512.3 100 - 1500A Skena: 50 x 12 mm 2 x 40 x 10 mm</p>
	<p>8A615.3 200 - 1600A Skena: 60 x 15 mm 2 x 50 x 10 mm 40 x 40 mm</p>		<p>9A615.3 200 - 2500A Skena: 50 x 12 mm 2 x 40 x 10 mm</p>		<p>9A640.3 200 - 2000A Skena: 60 x 40 mm 50 x 50 mm</p>
	<p>10A815.3 400 - 2500A Skena: 80 x 15 mm 2 x 60 x 10 mm 3 x 50 x 10 mm</p>		<p>10A830.3 500 - 2000A Skena: 60 x 60 mm 2 x 80 x 10 mm</p>		<p>13A1030.3 400 - 4000A Skena: 80 x 64 mm 2 x 100 x 10 mm</p>
	<p>13A1056.3 400 - 4000A Skena: 3 x 100 x 12 mm</p>		<p>16A1234.3 400 - 4000A Skena: 80 x 80 mm 2 x 120 x 10 mm 3 x 100 x 10 mm</p>		<p>13A1056.3 400 - 4000A Skena: 3 x 100 x 10 mm</p>